



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
February 1, 2006

Supervisor 

Mine Name: Koosharem Clay Mine

Operator Name: Paradise Management, Inc.
(Contract mined by Peck & Sons)

Inspector(s): Lynn Kunzler, DOGM

Other Participants: none

Mine Status: Active

Permit number: M/031/002

Inspection Date: August 18, 2005

Time: 4:00 pm

Weather: Clear

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This inspection was done to document site conditions while in the area.

Inspection Summary:

1. While no one else was on site during this inspection, the site is considered active - equipment was observed in the pit. This site recently received final approval of the LMO-NOI. Mining activity appeared to be following the plan.
8. Soils have been stripped above the highwall area and are stored in a berm (abt. 4 feet high) above the highwall. This soil berm also acts as a protection measure to keep public from the highwall.

Conclusions and Recommendations:

Continue to monitor this site when in the area. At this time, this operation is in compliance.

Photos were taken to document conditions.

Inspector's Signature 

LK:pb

O:\M031-Piute\M0310002-Koosharem\inspections\insp-08182006.doc

Date: February 1, 2006